CIVIL-TECH CONSULTANTS AND ENGINEERS

ABSTRACT OF FREQUENCY OF TESTS CARRIED OUT

Name of Work : BBMP Assets Fencing of Vacant BBMP Land (Including Parks Play Grounds and Garden) Ward No.07, BBMP, Bangalore.

Type of Road Surface	Minimum Number of Tests as per IRC norms	Number of Test done during execution	Percentage of Tests carried out as per IRC norms
I	II	III	IV
CIVIL WORKS	21	21	100%
TOTAL	**21**	**21**	**100%**

Scanned by TapScanner

ABSTRACT OF FREQUENCY OF TESTS CARRIED OUT

Name of Work : BBMP Assets Fencing of Vacant BBMP Land (Including Parks Play Grounds and Garden) Ward No.07, BBMP, Bangalore.

Description	Quantity	Unit	Total Number of test to be carried out as per IRC	Actual Number of Test to be conducted	% Completed
I	II	III	IV	V	IV
1) PCC 1:3:6 a)Cement b)M.Sand c)40MM Aggregates d)20MM Aggregates e)Sand(Mortar) f)Sand Plastering	80.85	Cum	6	6	100%
2)CC Block 400x150x200mm Compressive Strength & Density	152.4	Sqm	2	2	100%
3)Steel 8, 10 & 12mm	0.5	Tonne	3	3	100%
4)Cube M-20	5.03	Cum	3	3	100%
5)MS Angle 65x65x6mm	1205.6	Meter	1	1	100%
6)MS Block Pipe-38mm Dia	4327.75	Meter	1	1	100%
7)Chainlink Fencing-8 Gauge	3536.22	Sqm	1	1	100%
8)Cube M-15	32.04	Cum	4	4	100%
TOTAL			**21**	**21**	**100%**

Scanned by TapScanner